



Spax screw, countersunk head



- > Fully threaded (*partially threaded)
- > Countersunk head with PZ cross slot
- > Yellox coated

Spax screw, countersunk head



- > Fully threaded (*partially threaded)
- > Countersunk head with T star
- > Stainless steel

| Ø x Length/Thread | Driver required | Cat. No. | Order Qty |
|-------------------|-----------------|------------|-----------|
| 3.5 x 25 mm | TS15 | 018.55.089 | 200 |
| 3.5 x 30 mm | TS15 | 018.55.091 | 200 |
| 3.5 x 35 mm | TS15 | 018.55.093 | 200 |
| 3.5 x 40 mm | TS15 | 018.55.094 | 200 |
| 4.0 x 20 mm | TS20 | 018.55.116 | 200 |
| 4.0 x 25 mm | TS20 | 018.55.119 | 200 |
| 4.0 x 30 mm | TS20 | 018.55.121 | 200 |
| 4.0 x 35 mm | TS20 | 018.55.123 | 200 |
| 4.0 x 40 mm | TS20 | 018.55.124 | 200 |
| 4.0 x 45 mm | TS20 | 018.55.125 | 200 |
| 4.0 x 50 mm | TS20 | 018.55.126 | 200 |
| 4.5 x 40 mm | TS20 | 018.55.154 | 200 |
| 4.5 x 50 mm | TS20 | 018.55.156 | 100 |
| 5.0 x 30 mm | TS20 | 018.55.181 | 200 |
| 5.0 x 40 mm | TS20 | 018.56.184 | 200 |
| 5.0 x 50 mm | TS20 | 018.56.186 | 200 |
| 5.0 x 60 mm | TS20 | 018.56.188 | 100 |
| 5.0 x 80 mm | TS20 | 018.56.191 | 100 |
| 5.0 x 100/61* mm | TS20 | 018.55.193 | 100 |
| 6.0 x 60/37* mm | TS20 | 018.55.218 | 100 |
| 6.0 x 70/41* mm | TS20 | 018.55.220 | 100 |
| 6.0 x 100/60* mm | TS30 | 018.55.523 | 100 |



Please order screws in multiples of order quantity shown



- > Screwdrivers and driver bits are shown on page 60
- > Imperial to metric screw size conversion chart shown on page 8

| Ø x Length/Thread | Driver required | Cat. No. | Order Qty |
|-------------------|-----------------|------------|-----------|
| 3.0 x 12 mm | PZ1 | 018.01.051 | 200 |
| 3.0 x 16 mm | PZ1 | 018.01.054 | 200 |
| 3.0 x 20 mm | PZ1 | 018.01.056 | 200 |
| 3.0 x 25 mm | PZ1 | 018.01.059 | 200 |
| 3.0 x 30 mm | PZ1 | 018.01.061 | 200 |
| 3.0 x 35 mm | PZ1 | 018.01.063 | 200 |
| 3.0 x 40 mm | PZ1 | 018.01.064 | 200 |
| 3.5 x 12 mm | PZ2 | 018.01.081 | 200 |
| 3.5 x 16 mm | PZ2 | 018.01.084 | 200 |
| 3.5 x 20 mm | PZ2 | 018.01.086 | 200 |
| 3.5 x 25 mm | PZ2 | 018.01.089 | 200 |
| 3.5 x 30 mm | PZ2 | 018.01.091 | 200 |
| 3.5 x 35 mm | PZ2 | 018.01.093 | 200 |
| 3.5 x 40 mm | PZ2 | 018.01.094 | 200 |
| 3.5 x 45 mm | PZ2 | 018.01.095 | 200 |
| 3.5 x 50/40* mm | PZ2 | 018.01.096 | 200 |
| 4.0 x 16 mm | PZ2 | 018.01.114 | 200 |
| 4.0 x 20 mm | PZ2 | 018.01.116 | 200 |
| 4.0 x 25 mm | PZ2 | 018.01.119 | 200 |
| 4.0 x 30 mm | PZ2 | 018.01.121 | 200 |
| 4.0 x 35 mm | PZ2 | 018.01.123 | 200 |
| 4.0 x 40 mm | PZ2 | 018.01.124 | 200 |
| 4.0 x 45 mm | PZ2 | 018.01.125 | 200 |
| 4.0 x 50 mm | PZ2 | 018.01.126 | 200 |
| 4.0 x 60 mm | PZ2 | 018.01.128 | 100 |
| 4.0 x 70/50* mm | PZ2 | 018.01.130 | 100 |
| 4.5 x 25 mm | PZ2 | 018.01.149 | 200 |
| 4.5 x 30 mm | PZ2 | 018.01.151 | 200 |
| 4.5 x 35 mm | PZ2 | 018.01.153 | 200 |
| 4.5 x 40 mm | PZ2 | 018.01.154 | 200 |
| 4.5 x 45 mm | PZ2 | 018.01.155 | 200 |
| 4.5 x 50 mm | PZ2 | 018.01.156 | 200 |
| 4.5 x 60 mm | PZ2 | 018.01.158 | 100 |
| 4.5 x 70/59* mm | PZ2 | 018.01.160 | 100 |
| 5.0 x 25 mm | PZ2 | 018.01.179 | 200 |
| 5.0 x 30 mm | PZ2 | 018.01.181 | 200 |
| 5.0 x 40 mm | PZ2 | 018.01.184 | 200 |
| 5.0 x 45 mm | PZ2 | 018.01.185 | 200 |
| 5.0 x 50 mm | PZ2 | 018.01.186 | 200 |
| 5.0 x 60 mm | PZ2 | 018.01.188 | 100 |
| 5.0 x 70 mm | PZ2 | 018.01.190 | 100 |
| 5.0 x 80 mm | PZ2 | 018.01.191 | 100 |
| 5.0 x 90/60* mm | PZ2 | 018.01.492 | 100 |
| 5.0 x 100/60* mm | PZ2 | 018.01.493 | 100 |
| 6.0 x 60 mm | PZ3 | 018.01.218 | 100 |
| 6.0 x 70 mm | PZ3 | 018.01.220 | 100 |
| 6.0 x 80 mm | PZ3 | 018.01.221 | 100 |
| 6.0 x 100/60* mm | PZ3 | 018.01.523 | 100 |
| 6.0 x 120/68* mm | PZ3 | 018.01.525 | 100 |
| 6.0 x 140/68* mm | PZ3 | 018.01.227 | 100 |
| 6.0 x 150/68* mm | PZ3 | 018.01.228 | 100 |